





## INSPECTION EQUIPMENT

Cleaning Kit with hand microscope		
P.N	Description	Image/Photo
1069731	Complete inspection set, cleaning kit, hand microscope including universal adapter 1.25mm and 2.5mm for free APC/PC connectors	
<b>Delivery list - 1069731</b>		
I.P	Hard case	
1048757	Empty sectioned plastic box 17X12X3.5 cm	
I.P	Inspection microscope with universal adapter $\varnothing$ 2.5 mm, $\varnothing$ 1.25 mm (without soft case)	
I.P	$\varnothing$ 1.25mm adapter PC for free simplex connectors	
I.P	$\varnothing$ 2.5mm adapter PC for free simplex connectors	
1038981	CLETOP esay clean cassette Type B	
1038970	Replacement reel for Cletop Cassette Cleaner Type B	
1065369	Cletop cleaning sticks L=150mm $\varnothing$ 2.5 5pcs	
1020857	Cletop cleaning sticks L=150mm $\varnothing$ 1.25 5pcs	
1071628	Visual Fault Locator (ML3) Pen style	
1070135	Alcohol dispenser 150ml without alcohol	
1070137	Spender box with fibre optic lint-free wipes 10x10 cm 100 pcs.	
1070130	Fibre optic lint-free wipes to refill spender box 100pcs.	
1070125	Standard IBC-M250 for in adapter cleaning 2.5mm PC/APC	
1070131	IBC-1.25 for in adapter cleaning (1.25mm PC/APC)	

1019034	Service Adapter E-2000™	
1019483	Service Adapter F-3000™	

P.N	Description	Image/Photo
<b>Options for cleaning Kit with hand microscope</b>		
I.P	F-3000™ Adapter 0° for free simplex/duplex connectors <i>(With this adapter on the hand microscope, it is possible to inspect PS &amp; APC as well with an acceptable quality)</i>	
I.P	E-2000™ Adapter 0° for free simplex/duplex/Revos connectors <i>(With this adapter on the hand microscope, it is possible to inspect PS &amp; APC as well with an acceptable quality)</i>	
I.P	Ø3.175mm SMA Adapter PC for free simplex connectors	
1030609	Seikoh Giken Ferrule cleaner "Ferrule Mate", 2,5 mm	
1038865	Seikoh Giken Ferrule cleaner "Ferrule Mate", 1,25 mm	